

User's manual

Manual del usuario

Manuel de l'utilisateur

Customer Service
US: 1-800-645-2986

Servicio de atención al Cliente
US: 1-800-645-2986

Service à la clientèle
Canada: 888-645-2986

Digital Crane Scale With Remote

Models: 412597, 412598, 412604, 412605



Model	Product Description
412597	LED Digital Crane Scale With Remote 1,000 lb x 0.2 lb
412598	LED Digital Crane Scale With Remote 3,000lb x 1lb
412604	LED Digital Crane Scale With Remote 500lb x 0.2lb
412605	LCD Digital Crane Scale with Remote, 3,000 lb x 1 lb

Digital Crane Scale

Table of Contents

Instruction	3
Technical parameter	3
Battery instructions.....	3
Referenced dimensions	3
Operation Instructions	5
Power on	6
Power off	6
Zero	6
Tare.....	6
Hold.....	6
Advanced operation	6
2nd Mode.....	6
Accumulation function	7
Weight display	7
Switching between lbs./kg.....	7
4.5 Preset tare weight	8
Parameter setting	8
Battery power level checking	9
Internal code checking	9
Troubleshooting Display Codes	10

Digital Crane Scale

Instruction


Technical parameter

Accuracy class	III
Tare range	100% max. capacity
Initial zero range	±10% max. capacity
Manually zero range	±2% max. capacity
Operation temperature & humidity	14 - 104°F; ≤90% Relative Humidity (RH)
Storage temperature	-40 - 158°F

Battery instructions

The crane scale uses a 6v/4.5Ah rechargeable battery and lasts for about 80-150 hours. The battery charging port and battery indicator are on the back of the crane scale. The scale fully charges within 8-12 hours. The battery indicator turns from yellow to green when fully charged.

Referenced dimensions














Digital Crane Scale

Model No.	Product Description	Maximum Capacity (lbs.)	Division (lbs./kgs)	Size LxWxH (inches)	Weight
412604	LED Digital Crane Scale With Remote 500lb x 0.2lb	550	0.2/0.05	8.5"x 5.75"x15.16"	10.14
412597	LED Digital Crane Scale With Remote 1,000 lb x 0.2 lb	1100	0.2/0.1	8.5"x 5.75"x15.16"	10.14
412598	LED Digital Crane Scale With Remote 3,000lb x 1lb	3300	1/0.2	8.5"x 5.75"x17.13"	15.43
412605	LCD Digital Crane Scale with Remote, 3,000 lb x 1 lb	3300	1/ 0.2	8.5"x 5.75"x17.13"	15.43

Digital Crane Scale

Operation Instructions


Key/ function	Weighing mode	2nd mode	Data input	Parameter setting
	On/Off	Exit		Exit
	Zero	kg/lb unit change	Add 1 to the data	page up
	Tare	Preset tare weight	cursor flashing to the right	
	Hold	Parameter setting	confirm	Enter to next step
	2nd	Calibration mode		
	Accumulate		Reduce 1 to the data	Page down
	Clear last accumulation	Clear all the accumulation	cursor flashing to the right	
	Check the accumulation	Check the battery		
	serial interface send the data once	Set the serial interface		
	Check the last weight	Check the internal code		
	Store the weight			

Digital Crane Scale

Power on

Press the power button  for 1 second.



Power off

Press the power button . The scale will turn off automatically if not used for 30 minutes.



Zero

Press the zero button  to zero the scale.

Tare


Press the tare button  to enter the net weight mode. The new net weight will display as zero. Press the tare button  again to return to the gross weight mod and display the gross weight.

Hold

Press the hold button  to keep the current weight on the display. Press the hold button  again to stop holding the weight on the display. If an object is blocking the display while it is weighed, this function can help you view the object's weight after it's removed.

Advanced operation


2nd Mode


Some buttons have a 2nd function. Press the 2nd button  then press a different button to use its 2nd function. [2nd] will be displayed on the screen when the 2nd button is activated.


Press the power button  to exit.



Digital Crane Scale

Accumulation function


Load a weight on the scale until it is stable. Press the accumulation button  to add the current weight to an accumulative total. The display will read [ACC]. If the max weight has been reached, no more weight measurements can be added and the display will read [noACC].




Press the delete button  to remove the last added weight from the accumulated total. The display will read [DEL] when the last weight was removed; If there is no weight to remove, the display will read [noDEL].


Press  to see the number of weights added to the accumulated total displayed as [n***]. Then the total accumulated weight will be shown for 3 seconds before returning to the weighing screen.

Press the [2nd]  button then the delete button  to clear all the accumulation data. The display will read [CLEAR] to confirm all the weights were deleted.

Weight display

Press  to save the current weight value. [STORE] will be displayed when the weight is saved.

Press  to see the last weight saved, [LAST0]. Press  or  to look through the other saved weights. The most recent weight saves as 0 and the first weight saved as








9. Press  to display the corresponding weight for 2 seconds. The display will return back to weighing mode.

Switching between lbs./kg





Press the [2nd] button  then press  to convert the weight unit between lbs. and kg.

Digital Crane Scale

4.5 Preset tare weight

Press the [2nd] button  then press . The display will read [00000]. Use these keys     to input a tare weight value. Then press  to confirm the input value. The crane scale will enter the net weight mode.

Parameter setting


Press the [2nd] button  then press  to adjust the following settings: adjust division, delay automatic off, delay idle, filter intensity, display brightness, zero range, stable intensity, hold mode, warning tone, kg/lb conversion. After each operation, press  to confirm. Press  to exit.

Content	Display	Parameter instruction	Default value
Display division	E	0.02 = 0.02kg/lb 0.05 = 0.05kg/lb 0.1 = 0.1kg/lb 0.2 = 0.2kg/lb 0.5 = 0.5kg/lb 1 = 1kg/lb 2 = 2kg/lb	1
Automatic power off	OFF	00 = close this function 10 = 10 minutes delay 30 = 30 minutes delay 60 = 60 minutes delay 90 = 90 minutes delay	10
Idle mode ¹⁾	IDL	00 = close this function 10 = 10 minutes delay 30 = 30 minutes delay 60 = 60 minutes delay 90 = 90 minutes delay	30
Kg/lb conversion	UNS	0 = kg/lb conversion off 1 = kg/lb conversion on	1



Digital Crane Scale

Content	Display	Parameter instruction	Default value
Hold mode	HOLD	0 =close hold function 1 =Peak hold 2 =Data Hold 3 =Auto Hold 4 =Animal scale function	2
Zero range	ZERO	0=close manually zero setting and Initial zero range 1=Initial zero range \pm 10%, manually zero range \pm 2% 2= Initial zero range 100%, manually zero range 100%	1
Filter intensity	FIL	0=close the function 1=weak 2=moderate 3=strong	2
Stable intensity	STB	0=weak 1=moderate 2=strong	1
Warning tone	BEEP	0 close warning tone 1 open warning tone	1
Display brightness	LEDb	1=light 2= moderate 3=dark	1
Zero track speed	ZTS	0= no zero tracking 1= \pm 0.5d/s 2= \pm 1d/s 3= \pm 2d/s 4= \pm 5d/s	1

Battery power level checking

Press the [2nd] button  then press  to see the battery power level displayed in this format [U 6.**]. The display returns to weighing mode after 2 seconds.

Internal code checking

Press the [2nd] button  then press  to display the internal code for Maintenance and debugging.

Press the [2nd] button  then press  to return to the weighing mode.

Digital Crane Scale

Display Codes	Explanations
U 6.28	Battery power remaining.
oFF	Power off.
ACC	Weight added to accumulated total.
noACC	No more weights can be added to the accumulated total.
dEL	Clear the last accumulation value data.
nodEL	Cannot be cleared.
CLEAR	Clear all the accumulation data.
StorE	Save the display value data.
LASt0	See the last weight added to the accumulated total

Troubleshooting Display Codes

Display Codes	Cause	Solution
Err6	Exceed zero range.	Ensure the crane is not moving and press the zero button.
uuuuuu	Overload.	Reduce the weight.
nnnnnn	Weight measured is lower than the minimum value or the scale is moving.	Ensure the scale is not moving.
2nd	2 nd button pressed.	First press the 2 nd button then press another button to use its 2 nd function. Press the power button to cancel. Press the 2 nd button twice to enter the calibration mode.