

ONE PACKS

Dispenser-Free Control Systems®

Superlosa

B2310690

Medium-Duty All-Purpose Cleaner
Cleans Floors, Walls and Tables

Safe Handling

Avoid contact with eyes.

IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses if present and easy to do – continue rinsing. If eye irritation persists get medical attention.

Personal Protective Equipment: Wear protective gloves. Wear protective eyewear.



Unused Product Disposal: Unused product or its solution may be poured down the drain. Never pour unused product or its solution down an outdoor drain.

Improper dilution or improper use of this product may result in skin and eye irritation, damage to surfaces and unsatisfactory cleaning performance.

Pack Recycling: Empty packs should be rinsed out with cold water and then placed for recycling where accepted.



DIRECTIONS



Spray-and-Wipe. Mix each pack with 30 oz. (8.87 mL) of water for all-purpose spray-and-wipe cleaning.

Scrubbing and Damp Mopping. Mix with 1-2 gallons (4-8 L) of water for scrubbing or 2-4 gallons (8-15 L) for damp mopping.

Automatic Scrubber. Mix with 5 gallons (19 L) of water for automatic scrubber applications.

ONE PACKS

Dispenser-Free Control Systems®

Superlosa

B2310690

Limpiador Multiusos de Servicio Mediano
Limpia Pisos, Paredes y Mesas

Manejo seguro

Evite el contacto con los ojos.

EN CASO DE CONTACTO CON LOS OJOS: Aclare cuidadosamente con agua durante varios minutos. Quite las lentes de contacto, si lleva y resulta fácil. Sigue aclarando. Si persiste la irritación ocular: Consulte a un médico.

Equipo de protección personal: Lleve guantes de protección. Lleve gafas de protección.




Disposición del producto no usado: El producto no usado o sus soluciones pueden ser vertidos en el desagüe. Nunca vierta el producto no usado o sus soluciones en un desagüe exterior.

La dilución impropia o el empleo impropio de este producto pueden resultar en una irritación de la piel y de los ojos, en daño a superficies y en una limpieza insatisfactoria.

Reciclaje de paquete: Paquetes vacíos deberán ser enjuagados con agua fría y luego colocados para reciclar donde aceptado.



INTRUCCIONES



Pulverizar y limpiar. Mezcle cada paquete con 30 onzas (8.87 mL) de agua para usar con botella atomizadora para limpiar y secar.

Fregado y trapeado húmedo. Mezcle con 1-2 galones (4-8 L) de agua para el fregado o 2-4 galones (8-15 L) para trapear.

Depurador Automático. Mezcle con 5 galones (19 L) de aplicaciones de lavado automático.