



www.globalindustrial.com

US: 888-628-3466

Canada: 888-645-2986

Mexico: 01.800.681.6940

# Extra Long Assembly Workbench Assembly Instruction

## CONTENTS

| Ref. | Qty. | Description                    |
|------|------|--------------------------------|
| 1    | 1    | Bench Top Assembly             |
| 2    | 2    | Inner Leg                      |
| 3    | 2    | Outer Leg                      |
| 4    | 4    | Leg Support                    |
| 5    | 1    | Lower Shelf                    |
| H1   | 22   | 1/4-20 X .5" Lg Hex Head Bolt  |
| H2   | 22   | Plain Washer                   |
| H3   | 16   | 1/4-20 Serrated Flange Hex Nut |

Swing legs up as shown and attach with hardware provided

